

Download Sip Arc Welder User Manual

View and Download Sip Weldmate T251P user manual online. Arc Welder. Weldmate T251P Welding System pdf manual download. ... These SIP arc welders are covered by a 12 month parts and labour warranty covering IMPORTANT INFORMATION: These units can be set to deliver different output currents at failure due to manufacturers defects. Read all of these instructions before operating the inverter welder and save this user manual for future reference. The inverter welder should not be modified or used for any application other than that for which it was designed. This inverter welder was designed to supply electric current for ARC and TIG welding. When using your inverter welder, basic safety precautions should always be followed to reduce the risk of personal injury and / or damage to the welder. Ref. No. Description Sip Part No. Read all of these instructions before operating the welder and save this user manual Black cap 05147 for future reference. Read all of these instructions before operating the welder and save this user manual for future reference. The welder should not be modified or used for any application other than that for which it was designed. This welder was designed to supply electric current for Tig or Arc welding.