

Download Leisure Bay Hot Tub Owners Manual Model Number Lb501s

This Manual Contains IMPORTANT SAFETY INSTRUCTIONS ... An important WARNING sign is packed with your Leisure Bay Spa. This sign must be posted in a prominent place in close proximity to the spa installation site immediately upon completion of spa installation. ... in hot tubs or spas. Leisure Bay Replacement Circuit Board by Balboa, model LB501S VS501S, Chip LB501SR1A. OEM part number 53353-02. Controller part number is 53352. *THIS CIRCUIT BOARD IS OBSOLETE. CONSIDER REPLACING WITH A NEW SPAGUTS, BALBOA OR GECKO BRAND CONTROLLERS THAT COMES WITH A NEW TOPSIDE PANEL AND HEATER TO RETROFIT. CONTACT US FOR MORE INFORMATION. Leisure Bay's Model C Series spas are NOT EQUIPPED With A 240 Ground Fault Circuit Interrupter or a Disconnect Switch. Page 10 ELECTRICAL DATA FOR THE USE OF CERTIFIED LICENSED ELECTRICIAN WARNING: Shock Hazard! Under No Circumstances Should This Spa Be Installed By Anyone Other Than A Certified Licensed Electrician! Leisure Bay Spa Manuals, Spa Parts for All Spa Brands, Spa Jets, Spa Troubleshooting. Spaparts123 Service Help Center: Please Email Technical Questions to Support@Spaparts123.net. Leisure Bay Spa Manuals: Leisure Bay Spas Celebrity Manual: Click Here for Spa Parts SpaParts123.com: This Site is Designed to Help you Maintain Your Spa